



SERVICE NOTE

EFFECT: 2AXXON

NUMBER: 010 8/16/82

A typographical error has been identified on page 23 of the 2AXXON™ Owner's Manual (P/N 420-0724). The Part No. for IC No. MB3761 (top of the page) SHOULD READ: 313-0110, NOT 313-0101.